


File Options



## Main Menu

Production Test

Debug

Tune


Statistics

File Path


End Shift

Prod 4 Automated Test

## User Interface



## HP VEE Interface



Path (None Specified)

SID

N/A

Par

N/A


I

N/A

SWVer

N/A

User



# Prod-4 Communication

File Communication Special

Data Type

SID High/Low

EE Cus Option

Modem Trainiq

Poll Prod 4

TxD Counter

Net Number

EE Site Config

Modem AGC/RX AGC

Start Communication

Download to Prod4

Read SID

Status

EE HW Config

Link/Power/X0 Offset

Write SID

Start Tester SW

Command

Start up Subscriber

Write SID-NET-EE

Cal/Sync/Parity Err

Frequency

CRC Checksum

Net/Gen #

110 Baud

9600 Baud

Poll Message IDC dll

PC Prod-4 to Interface

Prod-4 to PC Interface

Prod-4 Command

PC Command